

APPENDIX-VIII

PERFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION
CERTIFICATE

No. : 194...

Date : 24.04.2025

It is Certificate that an inspection team headed by Mukesh Bai, Assistant Engineer
(Name of officers with designation) From P.H.E.D., D.S.D.-I, Thunhuny (Name of
Department/Office) inspected the Mahapragya International School (Name &
Address of the School) on 24.04.2025 and found that the Mahapragya International
School, Tamkar (Name of School) has safe drinking water facilities for the students
and members of staff of the institution and is maintaining the hygienic sanitation
condition in the school building & the campus as per the norms prescribed by the
Central/State/U.T. Govt.

The above valid a period of One year

Signature & Seal : [Signature]

Name : Mukesh Bai

Designation : [Stamp]

सहायक अभियन्ता

जन. स्वा. अ. विभाग

वि. व. व. व. प्रथम सुन्दर

अ. नं.-जे.जे.एन. 043

To,

Mahapragya International School,

Tamkar

.....

(Name & Address of the Institution)